

# Oil Field Environmental Incident Summary

**Incident:** 20140707141259      **Date/Time of Notice:** 07/07/2014 14:12

**Responsible Party:** ENCORE ENERGY PARTNERS OPERATING LLC

**Well Operator:** ENCORE ENERGY PARTNERS OPERATING LLC

**Well Name:** JENSEN 4 1

**Field Name:** MISSOURI RIDGE

**Well File #:** 6306

**Date Incident:** 7/5/2014      **Time Incident:** 09:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 155

**Rng:** 101

**Sec:** 4

**Qtr:**

**Location Description:** Flare pit at the Jensen 4-1 well facility.

**Submitted By:** Bart Brinkerhoff

**Received By:**

**Contact Person:** Ron Lassey  
Box 569  
powell, wy 82435

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Treater Popoff

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	30	Barrels	30	Barrels	30	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

Oil release into the flare pit.

**Inspected:**

**Written Report Received:** 11/25/2014

**Clean Up Concluded:** 7/7/2014

**Risk Evaluation:**

none. Fluid was removed from the flare pit. Could not rinse the pit on Monday due to wet weather.

**Areal Extent:**

***Potential Environmental Impacts:***

no environmental impacts. Pit will be flushed with fresh water. Oil release stayed in the flare pit.

***Action Taken or Planned:***

Stabilize the treater. Figure out the cause. Was it a dump valve etc.

***Wastes Disposal Location:*** Oil was put back into the production tank. Rinse water will be recycled or taken to approved disposal site.

***Agencies Involved:***

***Updates***

---

***Date:*** 7/7/2014      ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to a treater popoff, remained on location within the diking, according to the report. NDIC retains oversight.